Analytical Reference Materials International

Certificate of Analysis Certified Reference Material



Grade: Ti 5Al-2.5Sn / UNS R54520

Part Number (Q.A. NO.): IARM 271A

Certificate Date: 01/16/2007

Certificate No.: 271A-01162007-IARM-F

Revision Date: 10/03/2008

Interpretation of Data

- 1. Certified values listed below reflect analysis results submitted by qualified analytical laboratories using a combination of methods and instrumentation that emulate actual methods and instrumental techniques currently utilized in the analytical community and are reported as % wt. unless otherwise noted.
- 2. Any data reported and enclosed by a **parentheses** () is a "best estimate" and is NOT CERTIFIED. This data could not be quantified sufficiently for certification. It was however, reported by enough laboratories to be considered as potentially present in the matrix of the material being examined.
- 3. The "Inter-laboratory Analysis Program" (ILAP) utilized in the establishment of the data are an ongoing program with permanent membership. Certain elements may be selected by a consensus of the members for more extensive testing. Therefore the data in **brackets** [] indicates further testing is in process.
- 4. The "**±Estimated Uncertainty**" is enclosed by a **parentheses** () **below** the individual **element's concentration** and is based on a Confidence Interval at 95%. Included in this estimated uncertainty, are the combined effects of method imprecision, material inhomogeneity, and any bias between methods.

Important: A "User Registration Card" accompanies all shipments. This card should be completed immediately upon receipt of materials with the appropriate user information. This is the only way in which ARMI can guarantee customer updates or possible data modifications!

<u>Aluminum</u> 5.28 (0.03)	<u>Boron</u>	<u>Carbon</u> 0.026 (0.003)	<u>Chromium</u> 0.016 (0.002)	<u>Copper</u> 0.004 (0.001)	<u>Iron</u> 0.31 (0.01)	Hydrogen 0.013 (0.004)
<u>Manganese</u> 0.002 (0.001)	<u>Molybdenum</u> 0.011 (0.002)	<u>Nitrogen</u> 0.012 (0.001)	<u>Niobium</u>	<u>Nickel</u> 0.035 (0.002)	<u>Oxygen</u> 0.16 (0.01)	<u>Phosphorus</u> (0.002)
<u>Sulfur</u> (0.002)	<u>Silicon</u> 0.021 (0.002)	<u>Tin</u> 2.49 (0.02)	<u>Vanadium</u> 0.09 (0.005)	<u>Tungsten</u>	<u>Yttrium</u>	Zirconium 0.015 (0.001)

The laboratories participating in the "Inter-Laboratory Analysis Program" (ILAP) and certification of this material are as follows:

Alcoa Howmet, Research Center - Whitehall, MI	Anderson Laboratories, Inc Greendale, WI
ATI Allvac, Monroe - Monroe, NC	IMR Test Labs - Lansing, NY
Laboratory Testing, Inc Hatfield, PA	Massachusetts Materials Research - West Boylston, MA
Special Metals IncoTest - Hereford, UK	Stork Herron Testing Laboratories, Inc Cleveland, OH
Timet - North American Operations - Henderson, NV	Timet - North American Operations - Morgantown, PA
Timet - UK Limited - Witton, Birmingham, UK	Wah Chang - Albany, OR

Traceability: All members of the "Inter-Laboratory Analysis Program" (ILAP) listed above validate test methods and instrument performance utilizing SRMs produced by the National Institute of Standards and Technology, (NIST) as well as other CRMs and RMs produced by recognized Certifying Bodies from around the world. The specific SRMs, CRMs and RMs applicable to the material covered by this certificate are: NIST 173, 654B, ALPHA AR892, LECO 501-501, 501-674, 502-135, 502-154, NIST 654B, LECO 501-320, 501-676, 502-024, NIST654B, NIST 173C, 647, 648, IARM 174A, 174B, 175A, ALPHA AR 649, AR 881, LECO 501-320, P&W 31059, 31060, BCS 351, 454/1, 462/1, LECO 502-154, ALPHA AR637, 649, NIST 173B, 352C, BCS 357, 451/1, LECO 501-320, NIST 173A, 176, LECO 501-644, NIST 173A, 174A, 648, NIST 173C, 654B, 3107, 3112A, 3114, 3132, 3134, 3136, 3137, 3138, 3139A, 3161A, 3155, 3163, 3167A, 3169, BN 3840, LECO 762-741, ALPHA AR649, IARM 177A, 178A, BS TSU-1, TSU-2, NIST 15, OREMET 204, LECO 501-320, NIST 641, 642, 644, 646, 654B, 1128, 1131, IARM 175B, 177B, BS T-2, T-4, T-7, T-13, T-14, T-15, T-19, T-22, T-24, TX-4.

A specific line of traceability is established to NIST and other Certifying Bodies for those elements that are noted as "Certified Values" on the Certificates of Analyses referenced above.

See Reverse Side for Statistical Data and Additional Information Regarding this Material.

The following data and accompanying statements represent all pertinent information reported in the ILAP as it applies to the chemical characterization of this material as of 10/03/2008.

271A	AI	С	Cr	Co	Cu	Fe	Н	Mn	Мо	Ni	N	0	Pd	Р	Si
1	5.37	0.015	0.011	0.0026	0.0051	0.310	0.0226	0.00325	0.013	0.037	0.0143	0.1571	< 0.002	0.0027	0.013
2	5.22	0.0336	0.020	0.001	0.0020	0.305	0.0213	0.0033	0.0146	0.032	0.01126	0.156	< 0.010	0.0006	0.0231
3	5.305	0.0273	0.017	0.0014	0.0067	0.299	0.0155	0.0024	0.0088	0.034	0.0103	0.1744	<0.0008	0.0019	0.013
4	5.234	0.0288	0.0147	0.0010	0.0049	0.2977	0.0139	0.002	0.008	0.0329	0.0116	0.1746	0.0015	0.0020	0.022
5	5.23	0.0191	0.015	0.003	0.0038	0.292	0.0145	0.0015	0.0121	0.032	0.01161	0.1808	<0.01	0.0010	0.0215
6	5.20	0.0278	0.0197		0.0036	0.318	0.0082	0.0023	0.0122	0.036	0.0126	0.1560	<0.01		0.020
7	5.31	0.029	0.017		0.0042	0.306	0.0076	0.0028	0.012	0.0353	0.0118	0.16	< 0.005		0.024
8	5.236	0.028	0.019		0.0029	0.307	0.00687	0.0028	0.0146	0.0343	0.010	0.1626	< 0.0050		0.0222
9	5.32	0.0292	0.022		0.0036	0.312	0.008438	0.0010	0.0110	0.0390	0.0133	0.1770			0.020
10	5.316	0.0290	0.0156		0.0042	0.31095	0.0137		0.0081	0.0360	0.0090	0.156			0.023
11	5.288	0.02803	0.0103			0.317					0.0115	0.1590			0.0206
12	5.30	0.02823	0.0180								0.01267	0.1633			0.0240
13	5.268	0.0165	0.0155								0.01325				0.0220
Mean	5.2767	0.0261	0.0165	0.0018	0.0041	0.3068	0.0133	0.0024	0.0114	0.0349	0.0118	0.1647	0.0015	0.0016	0.0207
STDV.	0.0496	0.0261	0.0185	0.0018	0.0041	0.0081	0.0056	0.0024	0.0014	0.0023	0.0015	0.0093	0.0013	0.0018	0.0207
Certified	5.28	0.0030	0.0034 0.016	(0.0003	0.0013	0.0001	0.0030	0.0008	0.0024	0.0023	0.0013	0.0093		(0.0003)	0.0030
95% C.I.	0.03	0.020	0.010	(0.002)	0.004	0.01	0.013	0.002	0.002	0.002	0.012	0.10		(0.002)	0.021
Methods	X.I.O	C,O	X,I,O	X,I	X,I,O	X,I	F,O	X,I	X,I,O	X,I	F,O	F,O		1	X,I,O
wethous	11-														X,I,U
	l egend:	W = Classic	al C – Com	nhustion F	= Fusion	$\Delta = \Delta \Delta \text{ or } G$	FAA, I = ICP	or DCP D =	DC Arc (= OF X =	XRF G = G	$DMS. H = H_0$	ollow Catho	de OF	
	Logenai		,	,	= 1 usion,			,		,	,	,		40 01	
271A	Š	Sn	Ti	V	Y	Zr	В	Mg	Nb	Ru	Та	W	Yb	Pb	Sb
1	S 0.0020	Sn 2.56	Ti 90.5	V 0.087	Y <0.002	Zr 0.013	B <0.002	Mg <0.008	Nb 0.0033	Ru <0.010	Ta 0.0106	W 0.031			Sb
	S 0.0020 0.0033	Sn 2.56 2.50	Ti 90.5 91.54	V 0.087 0.091	Y <0.002 <0.0004	Zr 0.013 0.016	B <0.002 <0.0010	Mg <0.008 0.0003	Nb 0.0033 0.0024	Ru <0.010 0.0049	Ta 0.0106 <0.01	W 0.031 0.0121			Sb
1 2 3	S 0.0020 0.0033 0.0015	Sn 2.56 2.50 2.465	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108	Y <0.002 <0.0004 <0.0001	Zr 0.013 0.016 0.017	B <0.002 <0.0010 <0.0001	Mg <0.008 0.0003 <0.002	Nb 0.0033 0.0024 0.003	Ru <0.010 0.0049 0.0012	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01			Sb
1 2	S 0.0020 0.0033	Sn 2.56 2.50	Ti 90.5 91.54	V 0.087 0.091	Y <0.002 <0.0004	Zr 0.013 0.016	B <0.002 <0.0010 <0.0001 <0.0001	Mg <0.008 0.0003	Nb 0.0033 0.0024 0.003 0.002	Ru <0.010 0.0049	Ta 0.0106 <0.01	W 0.031 0.0121 <0.01 0.0006			Sb
1 2 3	S 0.0020 0.0033 0.0015	Sn 2.56 2.50 2.465	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108	Y <0.002 <0.0004 <0.0001	Zr 0.013 0.016 0.017	B <0.002 <0.0010 <0.0001	Mg <0.008 0.0003 <0.002	Nb 0.0033 0.0024 0.003	Ru <0.010 0.0049 0.0012	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01			Sb
1 2 3 4 5 6	S 0.0020 0.0033 0.0015 0.001	Sn 2.56 2.465 2.459 2.433 2.433	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 0.00063	Zr 0.013 0.016 0.017 0.0153 0.014 0.013	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005 0.0006	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005	Zr 0.013 0.016 0.017 0.0153 0.014	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020			Sb
1 2 3 4 5 6 7 8	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.465 2.459 2.433 2.433	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 0.00063	Zr 0.013 0.016 0.017 0.0153 0.014 0.013	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005 0.0006	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 0.00063 <0.0010	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005 0.0006 0.0012	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 0.00063 <0.0010 <0.01	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880	Y <0.002 <0.0004 <0.0003 <0.0005 <0.00063 <0.0010 <0.011	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9 10	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.089	Y <0.002 <0.0004 <0.0003 <0.0005 0.00063 <0.0010 <0.011 <0.00134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9 10 11	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51 2.487	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.089 0.0907	Y <0.002 <0.0004 <0.0003 <0.0005 0.00063 <0.0010 <0.011 <0.00134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9 10 11 12	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51 2.487 2.474	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.089 0.0907 0.109	Y <0.002 <0.0004 <0.0003 <0.0005 0.00063 <0.0010 <0.011 <0.00134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9 10 11 11 12 13	S 0.0020 0.0033 0.0015 0.001 0.0031	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51 2.487 2.447 4.2.50	Ti 90.5 91.54 91.778	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.089 0.0907 0.109 0.0880	Y <0.002 <0.0004 <0.0003 <0.0005 0.00063 <0.0010 <0.011 <0.00134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150	B <0.002 <0.0010 <0.0001 <0.0005 0.0006 0.0012 0.0003	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002	Ru <0.010 0.0049 0.0012 <0.005	Ta 0.0106 <0.01 <0.0020	W 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100			Sb
1 2 3 4 5 6 7 8 9 10 11 12 13 14	S 0.0020 0.0033 0.0015 0.001 0.0031 0.0020	Sn 2.56 2.405 2.445 2.433 2.460 2.51 2.489 2.442 2.51 2.487 2.474 2.50 2.536	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.076 0.082 0.088 0.087 0.0907 0.0880 0.0880 0.089 0.0907 0.109 0.0886	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.011 <0.00134 <0.000134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.0139	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005 0.0006 0.0012 0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020 <0.0100	Nb 0.0033 0.0024 0.003 0.002 0.0024 0.0024 0.0024 0.002	Ru <0.010 0.0049 0.0012 <0.005 <0.0050	Ta 0.0106 <0.01 <0.0020 <0.0100	₩ 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100 <0.0050			Sb
1 2 3 4 5 6 7 7 8 9 10 11 12 13 14 4 Mean	S 0.0020 0.0033 0.0015 0.001 0.0031 0.0020	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.412 2.51 2.487 2.51 2.487 2.536 2.4874	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.087 0.089 0.089 0.0907 0.109 0.0880 0.080 0.080 0.080 0.0808 0.0903	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.01 <0.00134 <0.000134 <0.0005	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.0139 0.0150	B <0.002 <0.0010 <0.0001 <0.0005 0.0005 0.0002 <0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020	Nb 0.0033 0.0024 0.003 0.002 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024	Ru <0.010 0.0049 0.0012 <0.005 <0.0050	Ta 0.0106 <0.01 <0.0020	₩ 0.031 0.0121 <0.01 <0.0020 <0.0020 <0.0100 <0.0050			Sb
1 2 3 4 5 6 7 8 9 10 11 12 13 14 Mean STDV.	S 0.0020 0.0033 0.0015 0.001 0.0031 0.0020	Sn 2.56 2.50 2.465 2.433 2.460 2.51 2.442 2.51 2.487 2.536 2.4874 2.536 2.4874 0.0351	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0880 0.0907 0.0880 0.0907 0.0880 0.0907 0.109 0.0880 0.0903 0.0903 0.0007	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.011 <0.00134 <0.000134	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.00150 0.0019	B <0.002 <0.0010 <0.0001 <0.0001 <0.0005 0.0006 0.0012 0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020 <0.0100	Nb 0.0033 0.0024 0.003 0.002 0.002 0.0024 0.002 0.0024 0.002 0.0025 0.0005	Ru <0.010 0.0049 0.0012 <0.005 <0.0050	Ta 0.0106 <0.01 <0.0020 <0.0100	₩ 0.031 0.0121 <0.01 0.0006 <0.0020 <0.0100 <0.0050			Sb
1 2 3 4 5 6 7 8 9 10 11 12 13 14 Mean STDV. Certified	S 0.0020 0.0033 0.0015 0.001 0.0031 0.0020	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51 2.487 2.474 2.50 2.536 2.536 2.4874 0.0351 2.49	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.0907 0.0880 0.0907 0.0880 0.0907 0.0880 0.0907 0.0880 0.0880 0.0867 0.0880 0.0867	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.01 <0.00134 <0.000134 <0.0005	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.0150 0.00150 0.00150 0.0015	B <0.002 <0.0010 <0.0001 <0.0005 0.0005 0.0002 <0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020 <0.0100	Nb 0.0033 0.0024 0.003 0.002 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024 0.002 0.0024	Ru <0.010 0.0049 0.0012 <0.005 <0.0050	Ta 0.0106 <0.01 <0.0020 <0.0100	₩ 0.031 0.0121 <0.01 <0.0020 <0.0020 <0.0100 <0.0050			Sb
1 2 3 4 5 6 7 8 9 10 11 12 13 14 Mean STDV. Certified 95% C.I.	S 0.0020 0.003 0.0015 0.001 0.0031 0.0020 	Sn 2.56 2.50 2.465 2.459 2.433 2.460 2.51 2.489 2.442 2.51 2.487 2.474 2.536 	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.0907 0.0880 0.0907 0.109 0.0886 0.0903 0.0087 0.0903 0.0087 0.0903 0.0087	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.01 <0.00134 <0.000134 <0.0005	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.0139 0.0150 0.0015 0.0015 0.001	B <0.002 <0.0010 <0.0001 <0.0005 0.0005 0.0002 <0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0020 <0.0100	Nb 0.0033 0.0024 0.003 0.002 0.002 0.0024 0.002 0.0024 0.002 0.0025 0.0005	Ru <0.010 0.0049 0.0012 <0.005 <0.0050	Ta 0.0106 <0.01 <0.0020 <0.0100	₩ 0.031 0.0121 <0.01 <0.0020 <0.0020 <0.0100 <0.0050			Sb
1 2 3 4 5 6 7 8 9 10 11 12 13 14 Mean STDV. Certified	S 0.0020 0.0031 0.0015 0.0015 0.0011 0.0020 0.0021 0.0020 0.0020 0.0020 0.0022 0.00022 0.00022 X,C	Sn 2.56 2.50 2.465 2.433 2.445 2.433 2.440 2.51 2.489 2.412 2.51 2.487 2.51 2.487 2.536 2.4874 0.0351 2.489 0.02 X,I,O	Ti 90.5 91.54 91.778 90.404	V 0.087 0.091 0.108 0.076 0.0822 0.088 0.087 0.0907 0.0880 0.0907 0.109 0.0880 0.0807 0.0903 0.0087 0.0903 0.009 0.009 X,I,O	Y <0.002 <0.0004 <0.0001 0.0003 <0.0005 <0.0010 <0.01 <0.00134 <0.0005 <0.0005	Zr 0.013 0.016 0.017 0.0153 0.014 0.013 0.0190 0.014 0.013 0.0190 0.014 0.0177 0.0150 0.0019 0.0150 0.0015 0.001 X,I,O	B <0.002 <0.0010 <0.0001 <0.0005 0.0005 0.0002 <0.0003 <0.0005	Mg <0.008 0.0003 <0.002 <0.0100 <0.0100 0.0003	Nb 0.0033 0.0024 0.003 0.002 0.002 0.0024 0.002 0.0024 0.002 0.0025 0.0005 (0.003) I	Ru <0.010 0.0049 0.0012 <0.005 <0.0050 0.0050	Ta 0.0106 <0.01 <0.0020 <0.0100	W 0.031 0.0121 <0.01 <0.0020 <0.0020 <0.0100 <0.0050	Yb	Pb	Sb

The International Standards Organization (ISO) definitions, expressed in ISO Guide 30-1992 list the following:

<u>Certifying Body:</u> Any technically competent body (organization or firm, public or private) that issues a reference material certificate which provides the information detailed in ISO Guide 31. The only generally accepted certifying body in the United States for primary standards - Standard Reference Materials (SRM) is the U. S. Department of Commerce, National Institute of Standards & Technology, (NIST), Gaithersburg, MD. All other certifying bodies in the United States produce Reference Materials (RM) or Certified Reference Materials (CRM).

<u>Reference Material (RM)</u>: Material or substance one or more of whose property values are sufficiently homogeneous and well established to be used for the calibration of an apparatus, the assessment of a measurement method, or for assigning values to materials.

<u>Certified Reference Material (CRM)</u>: Reference material, accompanied by a certificate, one or more of whose property values are certified by a procedure which establishes its traceability to an accurate realization of the unit in which the property values are expressed, and for which each certified value is accompanied by an uncertainty at a stated level of confidence.

Inter-Laboratory Analysis Program (ILAP): Although ASTM Standard E691-87 applies to inter-laboratory studies to "Determine the Precision of a Single Test Method", it is also a well thought out and logical plan for conducting an inter-laboratory program involving multiple techniques. Therefore, the planning, conducting, analyzing, protocol, and treatment of data resulting from this inter-laboratory program were performed utilizing the guidelines established in ASTM E691-87.

<u>Methods of Analysis:</u> In view of the fact, that the "Inter-Laboratory Analysis Program" entails a wide variety of materials, no single analytical method would provide optimum data results. Therefore, the methods utilized were a combination of ASTM Standard Methods for classical wet chemistry, ICP, AA, Optical Emission, and X-Ray spectrometric methods. The determinations for Carbon, Sulfur, Nitrogen, and Oxygen are the result of combustion instrument procedures.

Selection of Materials: A "batch" or "series" is defined as a single bar of one continuous length and heat. The majority of materials are in wrought condition; other methods of manufacture are utilized as a less desirable resort. ILAP samples are taken by removing a section, a minimum of, every one-twelfth of total length from the entire bar. A portion of the section is converted to chips and thin (pin) disk for analysis by classical wet chemistry, ICP, AA, and combustion procedures, and the balance remains as a thick disk for OES and X-Ray analysis. Each member of the ILAP is furnished a sample pack from a specific location on the batch bar. This systematic sampling procedure results in the homogeneity being reflected as a product of the overall statistics and certified data. This method of homogeneity testing is in accordance with ISO Guide 34, regarding the systematic selection and testing of a representative number of units for the assessment of homogeneity.

Certified by: Dillia

William D. Britt, President & General Manager Analytical Reference Materials International Corporation

Certificate No.: 271A-01162007-IARM-F Certificate Date: 01/16/2007 Revision Date/No.: 10/03/2008